


SAFETY DIRECTOR BULLETIN

WINTER SLIP AND FALL PREVENTION BEST PRACTICES



During the winter, the exposure to slip and falls dramatically increases due to weather conditions such as freezing rain, snow, and ice. Public agencies in New Jersey must plan to protect their workers and visitors from slipping on icy surfaces. This bulletin offers suggestions for a comprehensive program to minimize the hazards to employees, residents, and visitors.

An effective inclement weather plan aims to remove snow and ice from all walking surfaces and incorporate continuous surface monitoring and removal at critical times such as work start times, shift changes, and when melting and refreezing occur. Plans should be in writing and reviewed after every snow season. Pay special attention to common trouble spots such as parking areas, sidewalks, stairs, and ramps. About one-third of all slips on icy surfaces occur in parking areas.

If contractors are used, verify they have the proper levels of insurance. Work with your risk manager so the necessary certificates of insurance and hold harmless certificates are on file. Agencies should walk the areas to be cleared with contractors to identify features such as curb lines, speed bumps, drainage layouts, etc., and plan how and where snow and ice will be controlled.

Investigate pre-treatments and anti-icing agents. The science of chemical agents and delivery methods is constantly evolving. When deciding, evaluate guidance on anti-icing product effectiveness, temperature use, advantages and disadvantages, environmental impact, and cost per coverage area.

Use the same planning process if agency employees will be responsible for snow and ice control. We recommend using a site plan to designate areas for cleaning and should include curbs, fire hydrants, speed humps, walkways, and other items. This also facilitates updating your programs.

When possible, direct roof downspouts into underground drains versus being directed onto walkways, driveways, or other walking surfaces that could freeze.

Frequently inspect parking areas and sidewalks for:

- Lighting well-illuminated areas permit greater visibility to avoid icy areas.
- Drainage melt that cannot drain to sewers or grass will become ice when it refreezes.
- Dislocated or damaged items curbs, wheel blocks, and similar items are frequently moved or damaged by plows, creating new hazards to users.
- Cracks in the sidewalk snowmelt and water get into the cracks and freeze, and over time, repeated freezing and refreezing expands the crack, elevating the risk of trips and falls.

Also, remember that getting in and out of vehicles is one of the most frequent slip and fall exposures. Inspect vehicles to ensure step treads, running boards, and grab bars are in good condition.

Best Practices:

- Monitor weather forecasts. Do not be caught unaware of impending winter weather. Look for constancy in the forecast and follow meteorological guidance from professionals in the field. Many mobile weather apps only provide the forecast data of one model run, which provides data as much as two weeks out. If there is a forecast for a foot of snow a week out, the chances of that happening are very slim, but it is important to note there is at least a signal for the potential for winter weather. If you follow weather discussions from professionals, you will notice how they only start to provide their "first call" snow accumulation maps 48-72 hours before the event begins.
- When possible, barricade parking lots until they are entirely plowed and treated before permitting vehicles to park. This will prevent patches of ice between vehicles, which can present an ongoing slip-and-fall hazard to employees and visitors.
- Plan where to pile snow. Subsequent melting-refreezing cycles can create icy patches.
 - Do not block drains and downspouts.
 - Pile on the low side of walkways so run-off does not flow across paths of travel.
 - Do not create obstacles to pedestrian access areas such as bus stops and fire exits.
 - Utilize grassy areas, so run-off is absorbed into the ground.
- Talk to employees often about your commitment to preventing slip and fall injuries. Encourage them to report
 icy conditions and other concerns. Publicly acknowledge and thank those who do. Consider establishing a
 slip-trip-fall prevention committee during winter to focus on these hazards.
- Discuss footwear with employees. Does your policy permit reasonable exceptions to offer shoes for icy conditions? For employees who must work outside, there are many add-on devices to improve traction. Any employee clearing snow and ice should be encouraged to wear such devices. Consider them as Personal Protective Equipment. Inspect work boots to verify that the soles are in acceptable condition.
- Establish a monitoring system to spot black ice. Give special attention to walking surfaces during early morning hours, shift changes, or before employee and visitor arrivals.
- Provide salt/sand at entrances and expect employees to protect their welfare and the safety of visitors by using it and not waiting for someone else.
- Do not overlook lobbies and other entrances. Provide a sufficient number of caution or wet floor signs for vulnerable areas. Entryways should have recessed gridding or mats to scrape/clean shoe bottoms. Entrances should be monitored throughout the day and dry-mopped as needed.
- Transitioning from outside to inside presents different hazards. In addition to downward light from the sun, snow also reflects that light up, making it extra bright outside. Pedestrians need to adjust their gait as they move from outside sidewalks to inside flooring. Remind workers to walk with short, deliberate steps where the mid-foot strikes the ground first (not the heel). Eyes must also adjust from outdoor light (and glare) conditions to the interior light.
- Slips at the heel are the most common slip occurrence. When walking in slippery conditions, the body should be centered over the feet. Pay attention; do not become distracted with your phone, reaching for keys, etc. Avoid walking with your hands in your pockets or carrying large objects. Use railings whenever possible.
- Remind workers to look before getting out of their vehicles. If the area is icy, they may want to park in a different spot. Test potentially slippery surfaces by tapping with a foot before committing to them. Use the vehicle for support. Face the vehicle and follow the 3 Points of Contact rule. Always have both hands on the car when stepping into or out of the vehicle.

